

# How to float carbon foils

1. Use scalpel to cut carbon foil while still on the glass sheet
2. Slowly slide glass sheet into demineralised water using cotton swabs and a glass slide for support (if carbon foil won't let go, heat water to 30-40° C)
3. Gently lift the carbon foil out of the water at an angle of ~45 deg. Make sure all water runs off.

